## **Pacing Guide**

Week 1 Use breadboard to assemble wires to test all components Run "screen test" arduino code.	Begin soldering components (if comfortable soldering)  If no soldering experience, practice soldering	**Checkpoint** All components should be verified to be in working order.
Week 2 Complete soldering. Begin designing the case for laser cutting.	Complete laser cutting the case. Add any additional personalization (raster/paint/vinyl)	**Checkpoint** All soldering complete. Design for laser cut template complete.
Week 3 Explore supplied game code. Depending on time and experience level, change code to	**Checkpoint** Project complete	